

CORTROL 1.31.1 Release Notes

September 1, 2025

This is a maintenance version. Change log:

Improvements:

- Improved VCA search in archive playback mode by increasing search speed and accuracy
- Decreased startup time of the component updater on systems with restricted Internet access
- Improved Crosslink behavior for situations where the CORTROL Server starts faster than the network card, sometimes resulting in the configured URL failing to display
- Fixed colorful icons for Control Panels
- Localization updates for Polish language

Support for new cameras added:

- Mobotix Mx-VT1A-2-IR, Mx-VT1A-203-IR, Mx-VT1A-503-IR, Mx-VB1A-8-IR-VA, Mx-VD1A-8-IR-VA, Mx-BC2A-2-IR, Mx-VD2A-2-IR, Mx-VB3A-2-IR-VA, Mx-VD2A-2-IR-VA, Mx-VD2A-5-IR-VA, Mx-SD1A-540-IR-VA, Mx-SD1A-831-LIR-VA, Mx-SD2A-230-LL-FM-VA, M1A-S models
- Vivotek IB9383-HTV model
- Added support for the latest i-PRO firmware (3.45/2.85)

Fixes:

- The change of the maximized viewport channel in Console application is not taken into account when switching from Live to Playback mode
- When creating a new Control panel and adding new items to it, the new items are also added to the existing control panels until you close and reopen the previously opened control panels viewport in Console application
- Hard subtitles overlap during multi-channel export if there is an empty viewport at the subtitle position